

TECHNICAL NOTE NEW Concord 5" Touchscreen (60-924-3-C4TS5-2) with Firmware Patching Mechanism

1.0 Release Date: 10/21/2019

Subject:

NEW Concord 5" Touchscreen Version 2 with the firmware version above 2.1B is equipped with a new functionality allowing patching the panel from version 4.82 to version 4.82X. 4.82X is the functional equivalent of 4.83. Patch functionality works with: Concord 4 Residential and Concord 4 Commercial firmware version 4.82.

Info:

Patching Procedure

- 1. Connect the Concord 5" Touchscreen Version 2 with the firmware version above 2.1B to the Concord 4 panel Residential/ Commercial.
- 2. Turn on the Concord 4 panel by turning on AC power and connecting the backup battery.
- 3. Allow the Concord 4 panel to scan for bus devices.
- 4. Wait until the Touchscreen Version 2 displays the message "ATTENTION! Incompatible panel detected! Press here to perform panel patching."(The message will only appear in Concord 4 panel version 4.82)
- 5. Press the message displayed on the Touchscreen Version 2.





6. The patching process begins. Touchscreen Version 2 displays the message "Please Wait. The panel is being patched. Progress: X%." During the patching process the bus interface power supply will be reset once. (WARNING - DO NOT INTERRUPT THE PATCHING PROCESS. ANY INTERRUPTION MAY CAUSE DAMAGE TO THE PANEL FIRMWARE. THE PROCESS TAKES UP TO 20 SECONDS. EACH PANEL IS PATCHED ONE TIME.)



- 7. After the patching process, the Touchscreen Version 2 displays the message "ATTENTION! Panel successfully patched. Press here to confirm."
- 8. Press the message displayed on the Touchscreen Version 2. The panel patching process is finished.



- 9. Check the panel firmware version by following the steps below:
 - a. Press the Gear icon in lower right hand corner of the screen and scroll down to enter Programming:



Release Note: Interlogix. NEW Concord 5" Touchscreen with Firmware Patching Mechanism



b. Press the Programming button and enter in the Master or Programming Code:



c. Press the System Version button:



d. When the patch is successfully deployed, the System Version at the bottom of the screen should be 4.82X, which is the equivalent to 4.83.



WARNING:

- The process shall only be carried out by an Authorized Dealer/Installer.
- Any problem that was noticed during the operation should be reported to Technical Support.
- In case of error, please provide Technical Support with the error code.

Release Note: Interlogix, NEW Concord 5" Touchscreen with Firmware Patching Mechanism