RELEASE NOTE UPDATE
TruPortal™ 1.72.100

Release Date: 12/17/2018   Revision: 6.023

Contents

Introduction

This document specifies the differences and fixes introduced by the **1.72.100** truPortal release, as compared to the previous revision **1.72.96** and **1.72.99**. This document is an annex to the release note documents "**Relase_Notes_1.72.96.pdf**" and "**Release_notes_1.72.99.pdf**" which should be read first.

All the Sections of the document "**Release_Notes_1.72.96.pdf**" remain unchanged, except for the "New Features & Updates" and "Resolved Issues", which are updated below.

New Features and Updates

- Video device support extended. List of current DVR supported along with their firmware revisions:

Model	Supported FW Revisions
TVR10	2.7
TVR20	1.0.36
TVR11	3.1.b, 3.1.a, 3.0.d
TVR12	1.2.d, 1.2.c, 1.1.a
TVR12HD	1.2.j, 1.2.i, 1.2.g, 1.1.b, 1.0.i
TVR15HD	2.0.e, 2.0.b, 1.1.b, 1.1.a, 1.0.c
TVR45HD	2.1.b, 2.0.b, 1.1.a, 1.0.c
TVR40	3.2.d
TVR41	3.0.d, 3.0.c
TVR42	1.2.f, 1.2.e, 1.2.d
TVR44HD	1.2.j, 1.2.i, 1.2.g, 1.0.d
TVR60	4.7.a
TVN10	2.1.n, 2.1.l, 2.1.k, 2.1.i, 2.1.h, 2.1.g, 2.0.k, 1.1.g, 1.0.j
TVN11	1.0.e, 1.0.d, 1.0.c
TVN20	3.2.a
TVN21	3.1.m, 3.1.k, 3.1.j, 3.1.g, 3.0.i, 2.2.i, 2.1.a, 2.0.h,1.0.k
TVN22	2.2.b, 2.1.d, 2.1.b, 2.0.b, 1.0.e, 1.0.d
TVN50	2.2.j, 2.2.i, 2.1.a, 2.0.h,1.0.m
TVN70	1.2.n, 1.2.j, 1.2.i, 1.2.f, 1.1.b, 1.0.e
TVN71	1.1.e, 1.1.c, 1.1.b, 1.0.e

- **Adding support for EasyDDNS as a network configuration option**

Resolved Issues

- **The HTML5 interface doesn't allow certain values in the parity checking section of the card formats. You can add the formats with the flash interface but not in HTML5.**

- **If the default https port is changed, you cannot download a backup file from the panel.**

- **Fixed an issue with HTML5 address settings**

- **If you have a busy system that has a number of readers, and you wish to change access level assignments, it is impossible to select a schedule for the ones near the bottom of the list.**

- **Fixed an issue with the door display not being highlighted in red when a door tamper alarm was in effect.**

- **Fixed an issue that the user might not see the EULA in google chrome when first accessing truPortal**

Contact Information

www.interlogix.com
Customer support: www.interlogix.com/support