

**CareTaker® Plus**  
**Control Panel 60-435**  
**Interrogator™**  
**Alarm Verification**  
**Module 60-471**

Document Number: 46-745 Rev. A  
 March 1994

**N  
O  
T  
I  
C  
E**

 Interactive Technologies, Inc.  
 2266 North Second Street  
 North Saint Paul, MN 55109  
 Technical Services,  
 1-800-777-2624

ITI, Commander, and CareTaker are registered trademarks of Interactive Technologies, Inc. Interrogator is a trademark of Interactive Technologies, Inc.

## About This Document

This document describes the software requirements for the CareTaker Plus Control Panel when using the Interrogator Module combined with the 4/2 reporting format.

## Interrogator/CareTaker Plus Compatibility

When using an Interrogator Module with a CareTaker Plus Control Panel configured for 4/2 reporting format, the Panel must have software version 2.1\* or later installed for correct operation. CareTaker Plus Panels with earlier software versions that are configured for the 4/2 format, are not compatible with the Interrogator Module. Table 1 shows ITI Control Panel software support for the Interrogator Module.

Table 1. Control Panel Software vs. Interrogator Support

| Control Panel      | Software Version    | Compatible Reporting Formats with Interrogator |
|--------------------|---------------------|--|
| CareTaker Plus     | 1.0<br>2.0<br>2.1*  | None<br>ITI only<br>ITI and 4/2                |
| Commander®<br>2000 | All Versions        | ITI and 4/2                                    |
| SX-V               | Rev. K<br>and later | ITI only                                       |

## Version 2.1 Software Availability\*

We anticipate that CareTaker Plus software version 2.1 will be available in the second quarter of 1994. After all software testing is completed, we will issue an announcement including the part number and price for software version 2.1.