



# Interlogix – Simon XTi-5 V2 / Alarm.com® LTE Modem Interoperability Guide



## Introduction

- New Simon XTi-5 Version2 panels require Alarm.com modems with firmware 191c or later.

XT5 V2 panels have a gold sticker on the box, and “-2” at end of part number

Alarm.com modem box has revision on side label

Alarm.com modem not in box, has firmware revision on label



Rev. D

Rev. C (OTA\* required)



191

189 (OTA required)

**Table 1: Alarm.com Modem/Simon Panel Family Compatibility**

			Simon XT-5 V2 Panel	Simon XT5 Panel	Simon XTi Panel	Simon XT Panel
			80-632-3N-XT5-2	80-632-3N-XT5	80-632-3N-XTI	80-632-3N-XT
			80-632-3N-CN-XT5-2	80-632-3N-CN-XT5-2	80-632-3N-CN-XTI	80-632-3N-CN-XT
			80-649-3N-XT5-2	80-649-3N-XT5	80-649-3N-XTI	80-649-3N-XT
			80-632-3N-SP-XT5-2		80-517-3N-XTI	80-517-3N-XT
			80-632-3N-CNFR-XT5-2		80-517-3N-CN-XTI	80-517-3N-CN-XT
						600-1054-95R-CNSUM4
Alarm.com Modem	Modem Label Rev.	Modem F/W				
600-1048-XT-LTE-xx where xx -AT, -VT, -TL, -BC	Rev. D	191c	Compatible	Compatible	Compatible	Compatible
	Rev. C	189a	Compatible (OTA required)	Compatible	Compatible	Compatible
	Rev. B	189a		Compatible	Compatible	Compatible
	Rev. A	187i		Compatible	Compatible	Compatible
	Rev. A1	185		Compatible	Compatible	Compatible

**Note:** Over-the-air (OTA) modem upgrades require a minimum of 45 minutes to complete.

ALARM.COM® is a registered service mark of Alarm.com.