

TruVision DVR 12 Firmware 1.2 Release Notes

P/N 1072974-EN • REV A • ISS 21APR15

Introduction

This is the TruVision DVR 12 Firmware 1.2 Release Notes with additional information not covered in the user manual. For the latest information on the TVR 12 please visit:

Americas: <http://www.interlogix.com/videoupgrades>

EMEA: www.utcssecurityproducts.eu

Australia: www.interlogix.com.au

Overview

The TVR 12 is a 960 H Digital Video Recorder (DVR) for 4/8/16 analog cameras (including domes and PTZ). Firmware 1.2 introduces new features and defect fixes.

Summary of new features and key enhancements

- Added timeout feature for the Telnet port, the port will be disabled after 10 minutes.
- Include the full Player in the FW.

Summary of defects fixed

- Fixed translation error in record mode for language NL.

Contacting Support

For help installing, operating, maintaining, and troubleshooting this product, refer to this document and any other documentation provided. If you still have questions, contact us during business hours (Monday through Friday, excluding holidays).

Note: Please be ready at the equipment before calling.

Table 1: Technical support

North America	
T	+1 855.286.8889
E	techsupport@interlogix.com
W	www.interlogix.com/customer-support
Europe, Middle East, and Africa	
W	Select <i>Contact Us</i> at www.utcssecurityproducts.eu
Australia	
E	security.tech.support@interlogix.com.au
