

RELEASE NOTE UPDATE

TruPortal™ 1.8.0

Release Date: 04/23/2019 Revision: 6.024

Contents

Introduction	1
Added with 1.8.0	1
Contact Information	2

Introduction

This document specifies the differences and fixes introduced by the 1.80.0 truPortal release.

Added with 1.8.0

- Optimized IP door controller connection to truPortal, resolved many connectivity issues which resulted in temporary or long-term loss of connection.
- Legacy Flash-based User interface removed, a new user interface based on HTML5 is now the default browser user interface
- The HTML5 user interface can now be used on iOS devices in browsers
- Added the ability to read Facility Code from Cards presented to Readers on the main truPortal board.
- Removed redundant TVR names from the device list
- Added the One Time Event functionality – a one time schedule to unlock selected doors once for a given period of time
- Fixed an issue with Card formats not properly interpreting facility code for some card formats
- Changed the Language pack system – all available languages are now installed on truPortal by default
- Fixed an issue where the user could not download a backup file from the panel if the https port was not set to a default value
- Fixed a rare issue where the user could not add schedules if all the schedules were previously removed
- Fixed a rare issue with retrieving video from events where the a bad video clip was received
- Fixed an issue where the user could not view video on hybrid recorders when both analog and IP cameras were configured on the DVR device
- Fixed an issue where “Scan for Hardware Changes” feature didn’t name new devices properly
- Fixed an issue where adding a card from an “Invalid Credential Event” would add a credential with invalid data

Contact Information

www.interlogix.com

Customer support: www.interlogix.com/support

© 2019 United Technologies Corporation. Interlogix is part of UTC Climate, Controls & Security, a unit of United Technologies Corporation. All rights reserved.